# Spot II Checklist

Use SPOT Tracker on ALL CAP Flights and Vehicle travel out of your local area.  All button depresses require 3 second duration.

❑       Turn SPOT on by pressing the On/Off Button
               (To turn SPOT on, press the ON/OFF button.
                You must then wait an additional 2 minutes
                 before activating any SPOT function.
 When power is on, the indicator light will blink once every 3 seconds).

❑       **Activate 'Follow-Me' – (Press key with footprint)**
 Depress key for 3 seconds.
 On/Off button  and Follow-me key will blink every few seconds

❑       **Upon departure** Send a single Check-in/OK.
  (Press the OK √ button.)

❑       Upon location of Target of Mission Send the Custom Message(Target is here).
(Depress Message Cloud button)

❑       Upon arrival back to base location or mission base Turn off SPOT.
 (Depress On/Off for 3 seconds)

Remove SPOT from aircraft or vehicle glare screen and stow appropriately.

S.O.S button to be activated **only** on actual  emergency!

Help button to be activated if you are stranded with
 mechanical problems.

**Power button will flash red/green if batteries are low.**
**Only** Lithium AAA batteries are to be used.



ON/OFF

Non-Distress Help

Emergency (under cover)

Follow me

Check in / OK

Target is here